

Cultural Hub Design Update SEPTEMBER 2023

NO.	CHANGE	
DATE OF ISSUE - 16/08/2023		
1	Increased veranda width, from 3m to 4m at north-east end, to	
_	accommodate larger groups and potential for smoking ceremonies.	
2	Introduced gap to the north-eastern corner between 'chimney' and façade of building to provide	
	pedestrian access and visibility to southern side of the Coach House	
3	Repositioned service bay gates further west to provide pedestrian access to southern side of the Coach House	
4	Repositioned building to be 3.5m clear of existing eucalyptus tree at south west corner of site (viability of tree to be confirmed by council arborist)	
5	Lobby space reconfigured to provide increased access to merchandising and lounge for all	
	visitors, while maintaining ticketing	
	control for access to Pioneer Settlement precinct	
6	Reconfigured back of house area to include additional staff offices.	
7	Introduction of direct external access to/from Pioneer Settlement to the Aboriginal tourism	
	business/office space.	
8	Reconfigured 'chimney' elements with flat tops, in response to feedback from Council and community.	
9	Introduced north facing glazing to the back of house staff offices	
10	Introduced skylight to the lobby space to provide daylight	
11	Introduced retractable wall between the main lobby space and multi-purpose space	
12	Introduced external doors to the multi-purpose space to provide direct access to the Pioneer Settlement	
13	Investigation of use of recycled materials (ongoing) for landscape and building elements.	


DATE OF ISSUE - 04/09/2023

1	Revision of public toilet location, revision of 3 pans for male and female (1 ambulant compliant
	toilet in each)
2	Relocation of staff break room, revision of break room to prep kitchen
3	Introduction of meeting room for up to 6 users
4	Revision of provision for staff offices to the following
	 1 x office for 1 person
	 1 x office for 1 person, with direct access to bundling ,reception/ ticketing desk
	 1 x office for 3 person, with direct access to bundling
	reception/ticketing desk
5	Removal of shower from accessible toilet facility
6	Indication of location for interactive tourism information display
7	Relocation of staff lockers

DATE OF ISSUE - 16/08/2023


Reduction in length of building, increase distance from edge of building to Tree 1 by 1.5m, in 1 accordance with arborist recommendation

Swan Hill Tourism & Cultural Hub | Change Log | 06/09/2023





(-)




West Elevation



East Elevation






Swan Hill Tourism & Cultural Hub | Elevations | 06/09/2023



North Elevation



South Elevation





1. Red brick paver stacker bond

2. Red brick paver stretcher bond



3. Mottled grey masonry brick stacker bond



4. Milled hardwood timber seating block with inset powder coated steel



5. Cottage garden





5. Native Grassland Planting



TREE 1



TREE 2



TREE 3




TREE 4




TREE 5



TREE 6



New fence & after hours access gate





1. Entry plaza Internal foyer pavement connection exit & entry
 Cottage garden Connection plaza
 Outdoor seating - meeting and learning spaces 6. Services area

19


Realigned circulation road
 Shared connection path to Pioneer Settlement

9. Connection to Pental Island

10. Native grassland planting

Swan Hill Tourism and Cultural Hub | Landscape Plan | 1:250 @ A3

<u>/</u>____





5. Aluminum framed windows and glazed doors

1. Pressed Reds Brickwork

2. Heritage Zinc Wall Cladding

3. Perforated Heritage Zinc visual screening

4. Heritage Zinc Roof Sheeting







6. Timber sofits/eave linings (not shown)















